




Flexible aluminum sheet conductor was found like this after manually returning the busbar (in person). In the future, we should keep in mind to check this and 'tidy' it if needed.




Accessing top three screws on busbar












Second manipulator coming in to retrieve busbar screw, minor interference with shielding at the top.







Attempting to reach big screw for the busbar sheet, some interference between manipulator shaft and shielding above












Difficulty getting torque tool to access big screw due to clearance limitations












FE rotated to get a better view of the big screw











Manipulator arm interference with polished plate assembly





Using ratchet successfully 'loosened' big screw.






In this orientation, adjustable wrench not able to reach VCR on second to bottom line.







Cramped manipulators.






Two wrenches from one side



Interference with HV shield visible in this photo.
















VCR joint successfully seaprated



Sheet metal tool used to push the VCR nut up from U-bend











Female VCR nut 'stayed up' on its own eventually.







Orientation where VCR nut could be started with the manipulators without too much interference with the HV shield.





'Pinching' action to position the flexible line and keep the male side from rotating.






























VCR joint re-tightened.