


Loc	Target	Pail	Assay 1 [mSv/h]	A1 date	Assay 2 [mSv/h]	A2 date	Assay 3 [mSv/h]	A3 date	Assay 4 [mSv/h]	A4 date	Assay 5 [mSv/h]	A5 date	Assayed	Comment
1A	UC#30	238	81.5	2020-09-24									0	0
1B	UC#32	254	21.2	2021-07-09									0	0
1C	UC#33	255	39.9	2021-08-06									0	First one done from the NHC
2A														
2B	2A3M20#	252	0.2	2021-06-10									0	metal bits.
2C	C#3	270	37.9	2021-11-10									0	0
														This pail also contains, wire, a wirescanner, IGM guage, target bolts and water block
3A	ZrC#8	217	205.0	2019-10-02	74.8	2019-12-10							Measured	bolts
3B														
3C	Ta#58	211	311.0	2019-08-19	52.5	2019-12-10							Measured	0
4A	Ta#59	220	121.0	2019-11-08									0	0
4B														
4C	SiC#39	227	30.6	2020-03-06									0	Contamination might be on lid
5A														
5B	SiC#41	260	33.1	13/10/2021									0	0
5C														
6A	UC#35	264	25.7	2021-11-26									0	0
6B	Ta#61	245	41.6	2021-01-13									0	0
6C	Nb#9	246	149.0	2021-01-21									0	0
														Disc in bottom of pail was not installed pail will need repacking. This pail is likely contaminated and also contains 2A2M19.
7A	Ta#62	256	58.0	2021-09-17									0	
7B	Ta#60	239	83.2	2020-10-21									0	0
7C	UC#34	258	419.0	2021-09-22									0	0
8A	C#2	235	185.0	2020-11-19									0	0
8B														
8C														
9	TM4 optics tray 2018. TM2 source tray 2019		1.9	2018-06-14	14.0	2019-03-01	7.1	2020-11-02						In Source Tray Box. The 1.9 mSv/Hr value is just for the optics tray. All other values are for both Optics and Source tray.
10	TM4 Source tray		22.1	2019-06-10										7.5 to 22.1 mSv/hr on 360 rotation.

 Need to change pail to new design