Loc	Target	Pail	Assay 1	A1 date	Assay 2	A2 date	Assay 3	A3 date	Assay 4	A4 date	Assay 5	A5 date	Assayed	Comment
			[mSv/h		[mSv/h		[mSv/h		[mSv/h		[mSv/h]			
1A														
1B	UC#37	228	63.2	23/06/2022									0	0
1C	UC#33	267	39.9	8/6/2021	4.1	1/27/2022							Measured	First one done from the NHC pail changed
2A	UC#36	265	19.6	1/12/2022	10.7	1/28/2022							Measured	0
2B	SiC#42	271	9.1	7/6/2022									0	0
2C	C#3	270	37.9	11/10/2021	10.8	1/28/2022							Measured	0
														This pail also contains, wire, a wirescanner, IGM guage, target bolts and
3A	ZrC#8	217	205.0	10/2/2019	74.8	12/10/2019	3.1	1/31/2022						water block bolts
3B	Ta#63	266		20/01/2022									0	0
3C	Ta#58	211	311.0	8/19/2019	52.5	12/10/2019	7.1	1/31/2022					Measured	0
4A														
4B														
4C													•	•
5A	SiC#43	272	47.8	28/07/2022	7.0	1 /22 /222							0	0
5B	SiC#41	260	33.1	13/10/2021	7.8	1/30/2022							Measured	-
5C	Ta#64	273	86.6	8/18/2022		1 /24 /2022							0	0
6A	UC#35	264	25.7	11/26/2021	5.9	1/31/2022							Measured	
6B	Ta#61	245	41.6	1/13/2021	3.6	1/31/2022							Measured	
6C	Nb#9	246	149.0	1/21/2021	9.1	1/31/2022							Measured	U
70	Ta#62	256	E9.0	0/17/2021	16.0	1 /27 /2022							Massurad	Disc in bottom of pail was not installed pail will need repacking. This pail is likely contaminated and also contains 2A2M19.
7A	Ta#62 Ta#60	239	58.0	9/17/2021 10/21/2020	16.9 3.7	1/27/2022 1/27/2022							Measured	
7B 7C	UC#34	268	83.2 419.0	9/22/2021		1/27/2022								Pail changed from 258 to 268
8A	00#34	200	419.0	9/22/2021	4.7	1/2//2022							ivieasureu	Pail Changeu Hoffi 230 to 200
8B														
8C														
9	TM4 optics tray 2018. TM2 source tray 2019		1.9	6/14/2018	14.0	3/1/2019	7.1	11/2/2020						In Source Tray Box. The 1.9 mSv/Hr value is just for the optics tray. All other values are for both Optics and Source tray.
10	TM4 Sou tray	rce	22.1	6/10/2019										7.5 to 22.1 mSv/hr on 360 rotation.

Need to change pail to new design