





Interference of second top most line against busbar, prevents exchange.










Use of pi detent tool to manipulate the water line without scratching the sealing face.
























VCR nut obstructed by bus bar





Deep VCR for top most line.





Bottom most line has interference with other lines when attempting to remove