





12-point closed wrench on VCR nut.










Pin tool interfering with HTV post when using for the second to top line.






Second to top line being removed




















Second to top line returned in place.









Rear bus bar removed











Starting VCR joint on second to top line with difficulty





Wrench interference with adjacent line in second to top line's VCR joint







Nut falling in top line's VCR joint 'U' bend.













Bottom line catching on screws when returned/removed.