




Torque tool interference when accessing HV shielding for this hanging VCR joint.






Joint successfully re-done by hand, no need for manipulator testing.





Bracket issue requires improper mounting of the female VCR side.







Successful positioning of the flexible lines on the upper driver side with manipulators into bracket.





