


Wednesday, February 15, 2017
3:27 PM


2017-02-15

Post installation photo/video inspection:









Unable to pump because vac group working on inflector. Blank off was installed at 11:15.