ISAC Storage Vault Status as of October 8 2013

Tray #	Pail#	Target	Installed (m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
may m	T GII II	raiget	mstalled (m/d/y)	rteading (movirii)	Comments	Bute Removed	rteading(mov/m)	Commente
1A								
• • • • • • • • • • • • • • • • • • • •								
1B	94	SiC #26	05/05/12	118mSv/hr				
		010 1120	00/00/12	1101110 77111				
1C								
2A						-		
			10/08/13	24.7mSv/hr				
2B	109	SiC #29						
			05/31/13	24.8mSv/hr				
2C	105	SiC #28						
3A	96	SiC #27	07/06/12	178mSv/hr				
			09/29/11	111mSv/hr				
3B	90	Ta #36	06/20/13	4.64mSv/hr	Assayed			
					<u>-</u>			
3C								
			10/24/12	35.5mSv/hr				
4A	101	NiO #1	06/20/13	1.50mSv/hr	Assayed			
4B	104	TiC #3	01/15/13	98.7mSv/hr				
4C	106	Ta #39	07/02/13	95.3mSv/hr				
5A	107	Ta #40	07/29/13	224mSv/hr				
			01/11/11	230mSv/hr				
5B	85	Nb #5	06/20/13	3.05mSv/hr	Assayed			
			06/11/12	152mSv/hr				
5C	95	Nb #6						

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring and cable lifting setup. This ring must be locked with a thin piece of metal before shipping.

Tray #	Pail #	Target	Installed (m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
-			11/09/12	178mSv/hr			,	
6A	103	Nb # 7						
			08/02/12	226 mSv/hr	Bolts might be contaminated			
6B	97	Ta#38						
			07/25/11	411mSv/hr				
6C	88	Ta#35	06/20/13	8.26mSv/hr	Assayed			
7 A								
			11/16/11	239mSv/hr				
7B	92	TaC#1	06/20/13	3.55mSv/hr	Assayed			
			08/25/10	292mSv/hr				
7C	81	ZrC#5	06/20/13	2.65mSv/hr	Assayed			
8A								
8B								
		110 40	08/28/13	23.1mSv/hr				
8C	108	UC _x #6			_			_
Tray #	Description of Item		Date Installed	O (,	Comments	Date Removed	Reading(mSv/Hr)	Comments
	Used source tray			5.6 to 16.4	Tray surveyed on			
	from TM #2			mSv/hr thru	11/02/12			
				360°	2.07 to 4.39 mSv/hr			
					though 360°			
9			01/15/09					
	Used source tray			1.66 to 3.50	The source tray was			
	from TM #1			mSv/hr thru	taken apart for inspection			
				360°	Tray surveyed on			
					11/02/12			
			I		1.83 to 3.23 mSv/hr			
10			05/12/11		though 360°			

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.