


Loc	Target	Pail	Assay 1 [mSv/h]	A1 date	Assay 2 [mSv/h]	A2 date	Assay 3 [mSv/h]	A3 date	Assay 4 [mSv/h]	A4 date	Assay 5 [mSv/h]	A5 date	Assayed	Comment
1A	UC#30	238	81.5	9/24/2020									0	0
1B	UC#32	254	21.2	7/9/2021									0	0
1C	UC#33	255	39.9	8/6/2021									0	First one done from the NHC
2A	UC#36	265	19.6	1/12/2022									0	0
2B														
2C	C#3	270	37.9	11/10/2021									0	0
3A	ZrC#8	217	205.0	10/2/2019	74.8	12/10/2019							Measured	This pail also contains, wire, a wirescanner, IGM guage, target bolts and water block bolts
3B														
3C	Ta#58	211	311.0	8/19/2019	52.5	12/10/2019							Measured	0
4A	Ta#59	220	121.0	11/8/2019									0	0
4B														
4C	SiC#39	227	30.6	3/6/2020									0	Contamination might be on lid
5A														
5B														
5C														
6A	UC#35	264	25.7	11/26/2021									0	0
6B	Ta#61	245	41.6	1/13/2021									0	0
6C	Nb#9	246	149.0	1/21/2021									0	0
7A	Ta#62	256	58.0	9/17/2021									0	Disc in bottom of pail was not installed pail will need repacking. This pail is likely contaminated and also contains 2A2M19.
7B	Ta#60	239	83.2	10/21/2020									0	0
7C	UC#34	258	419.0	9/22/2021									0	0
8A	C#2	235	185.0	11/19/2020									0	0
8B														
8C														
9	TM4 optics tray 2018. TM2 source tray 2019		1.9	6/14/2018	14.0	3/1/2019	7.1	11/2/2020						In Source Tray Box. The 1.9 mSv/Hr value is just for the optics tray. All other values are for both Optics and Source tray.
10	TM4 Source tray		22.1	6/10/2019										7.5 to 22.1 mSv/hr on 360 rotation.

 Need to change pail to new design