







Peak force measured during coupling was ~1700N.









All pins on 48 pin connector coupled together without issue when the service tray was raised.



All pins self-guide into the sockets.

