

Project No. \_\_\_\_\_

Book No. \_\_\_\_\_

TITLE \_\_\_\_\_

Page No. \_\_\_\_\_

0568

APRIL 16/15

LEAK CHECK T2/TNF - BLOWER PACKAGE ON

UPSTREAM T2 WINDOW VALUE

FAST LEAK RATE 2.2 x 10<sup>-8</sup> 2.5 x 10<sup>-8</sup>

30 SEC	NO RESPONSE	30	NO RESPONSE
1min	NO RESPONSE	1	NO RESPONSE
130	NO RESPONSE	130	NO RESPONSE
2	NO RESPONSE	2	2.9 x 10 <sup>-8</sup>
		230	3.0 x 10 <sup>-8</sup>
		3	3.1 x 10 <sup>-8</sup>
		330	3.0 x 10 <sup>-8</sup>

INLET JOINT UPSTREAM T2 DEADLINE 1 2.9 x 10<sup>-8</sup>

30	NO RESPONSE
1	NO RESPONSE
130	NO RESPONSE
2	NO RESPONSE
230	3.0 x 10 <sup>-8</sup>

BLANK OFF M9 3.0 x 10<sup>-8</sup> 3.0 x 10<sup>-8</sup>

30	NO RESPONSE	30	NO RESPONSE
1	NO RESPONSE	1	5.2 x 10 <sup>-8</sup>
130	3.1 x 10 <sup>-8</sup>	130	4.8 x 10 <sup>-8</sup>
2	3.2 x 10 <sup>-8</sup>	2	4.4 x 10 <sup>-8</sup>
230	3.2 x 10 <sup>-8</sup>	230	3.8 x 10 <sup>-8</sup>
3	3.2 x 10 <sup>-8</sup>	3	3.5 x 10 <sup>-8</sup>

To Page No. \_\_\_\_\_

Invented & Understood by me,

Date

Invented by:

Date