



Tuesday, February 14, 2017

2015 vs 2017 T2 M9 flange comparison, looks roughly the same. The concern is the lower quadrant knife edge and counter bore from BDC (6 o'clock to 9-10 o'clock position).









08/04/2015 10:03:20

