

T2-MK2 Target Leak Check

March 14, 2013


Pumped down to 20 on Hastings Vacuum Gauge

Leak detector + lower hoses: No Response

Upper hoses: No Response

Val Flange Surgeplate Joints: No Response

Baseline 10 on x10 scale



Left Bellows: Up to ~13

Right Bellows: Up to ~17

- 1: N/R
- 3: N/R
- 5: N/R
- 7: N/R
- 9: N/R
- 11: N/R
- 13: N/R

- 2: Up to 18
- 4: N/R
- 6: N/R
- 8: N/R
- 10: Up to 17
- 12: N/R
- 14: N/R

Target Pos'n 3 Windows: N/R

Target Pos'n 4 Windows: N/R

~2s
 Larger ^v general spray in 1+3 area: N/R
 2+4 area: Up to ~50

Repeat spray on right bellows: Up to ~20

Back side of location #2: Up to ~55

Larger (~2s) spray in general area around location #10: Up to ~35