


Confirmed interference between tubes on upper VCR joints



Helicoil insert 'threaded out' and prevents screw on gas line bracket from being re-done.




Smal Allen key can be used to help guide bracket into location.






Gas lines have some tendency to 'wedge' in cutouts on the cable guides (see following pictures).
























Both lines successfully 'fished out'.







'catch point' when pulling out gas line.



