

TMZ NEW SOURCE Tray Water Blocks

leak check 2015-06-24

D: Tube Heater (+)

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No response on LD

C: Tube Heater (-)

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No response on LD

B: Target Oven (-)

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No response on LD

A: Target Oven (+)

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

~~Q: CO₂ +~~

Q: CO₂ +

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response

P: CO₂ -

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

I: EE

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

F: HS

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

M: GE

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

W: WINDOW

BLR: 0.0×10^{-9} atm.cc/sec

BP: 0.0×10^{-4} torr

No Response on LD

E: MSP

BLR: 0.0×10^{-9} atm. cc/sec

BP: 0.0×10^{-4} Torr

No response on LD

U: CO₁-

BLR: 0.0×10^{-9} atm. cc/sec

BP: 0.0×10^{-4} Torr

No response on LD

R: CO₁+

BLR: 0.0×10^{-9} atm. cc/sec

BP: 0.0×10^{-4} Torr

No response on LD

Each circuit
~~III~~

6 seconds helium in SHC by chad. F
spray