







**Pre Lid Down Cyclotron Video Survey -- 14/03/2013**

Orbit	Photograph		Description
275	IMG1265		Thermocouple Wire Hanging Down
308	IMG1268		Plastic Bag
271	IMG1270 IMG1271		<p>Housekeeping – Wiring – typical of wire weights, numerous need tlc – ensure wires are placed properly                      Consider for long range scheduling – no immediate urgency</p>

Pre Lid Down Cyclotron Video Survey -- 14/03/2013

Orbit	Photograph		Description
244.7	IMG1273		Debris – should be removed
282.0	IMG1274		Piece of glove or bootie
391.1	IMG1277 ScreenGrab		?String? bundle laying on resonator Upper #8 Quadrant 1 Resonator – approximately ½ out on leveling arm