

Lid up Operation	Date:	2024-05-02	Time Lift Started:	11:45	Master Synchro. Pre	66						
	Height Confirmation		Time Lift Ended:	12:13	Master Synchro. Post	47387						
Station	1	2	3	4	5	6	7	8	9	10	11	12
Pre-lift Synchro	70	67	73	63	36	70	71	74	104	45	69	66
During Lift												
Jogging	No Jogging Required											
Jog 1												
Jog 2												
Jog 3												
Inspection During Lift												
Seal stuck to lid		X										
@3" check tank seal												
Heat Check - After running for 20 minutes												
Left Highfield	No heat check performed											
Motor												
Right Highfield												
Post-lift Synchro												
	47369	47363	47368	47346	47328	47362	47365	47366	47389	47338	47356	47360
Notes	Lid up due to inflector vacuum sealing issue											