State of the ISAC Mini Storage Vault as of May 25 2012

Pail #	Target	Date Installed(m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
				first (back of mini storage)			
86	UC #1	05/25/12	0.19mSv/hr				
				second			
91	UC #2	05/25/12	1.12mSv/hr				
				third			
84	SiC #24	05/25/12	1.99mSv/hr				
				fourth			
68	Ta #27	05/25/12	2.76mSv/hr				
				fifth(front of mini storage)			
79	SiC #22	05/25/12	1.93mSv/hr				
							_
							_

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.