

Vault Target Storage

ISAC Storage Vault Status as of May 25 2012

Tray #	Pail #	Target	Installed (m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
1A								
1B	94	SiC #26	05/05/16	118mSv/hr				
1C	93	UC _x #3	03/13/12	11.7mSv/hr				
2A	87	SiC #25	05/31/11	120mSv/hr				
			12/15/11	10.7mSv/hr	Not Assayed			
2B	83	SiC #23	10/20/10	143mSv/hr				
			12/15/10	6.72mSv/hr	Not Assayed			
2C	82	Ta #34	10/20/10	93mSv/hr				
			12/14/11	4.33mSv/hr	Assayed			
3A								
3B	90	Ta #36	09/29/11	111mSv/hr				
3C								
4A								
4B	76	Nb #4	02/09/10	160mSv/hr				
			11/10/11	3.89mSv/hr	Assayed			
4C								
5A								
5B	85	Nb #5	01/11/11	230 mSv/hr				
5C								

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.
 All lids have the lever lock ring and cable lifting setup. This ring must be locked with a thin piece of metal before shipping.

Vault Target Storage

Tray #	Pail #	Target	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
6A								
6B								
6C	88	Ta#35	07/25/11	411mSv/hr				
7A	75	Ta#31	06/10/10 12/15/11	116mSv/hr 4.17mSv/hr	Assayed			
7B	92	TaC#1	11/16/11	239mSv/hr				
7C	81	ZrC#5	08/25/10 12/15/11	292mSv/hr 13.7mSv/hr	Not Assayed			
8A								
8B	78	Ta#32	07/16/10	124mSv/hr				
8C								
Tray #	Description of Item	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments	
9	Used source tray from TM #2	01/15/09	5.6 to 16.4 mSv/hr thru 360°					
10	Used source tray from TM #1	05/12/11	1.66 to 3.50 mSv/hr thru 360°	The source tray was taken apart for inspection				
All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.								
All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.								

Vault Target Storage

Vault Target Storage