ISAC Storage Vault Status as of August 2 2012

T					c vadit Ctatas as of Augu			
Tray #	Pail #	Target	Installed (m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
1A								
1B	94	SiC #26	05/05/12	118mSv/hr				
1C	93	UC _x #3	03/13/12	11.7mSv/hr		-		
		^	05/31/11	120mSv/hr				
2A	87	SiC #25	12/15/11	10.7mSv/hr	Not Assayed			
	07	010 #20	10/20/10	143mSv/hr	Not Assayed			
2B	83	SiC #23	12/15/10	6.72mSv/hr	Not Assayad			
2D	၀၁	SIC #23			Not Assayed			
		_ "0.1	10/20/10	93mSv/hr		-		
2C	82	Ta #34	12/14/11	4.33mSv/hr	Assayed			
3A	96	SiC #27	07/06/12	178mSv/hr				
			09/29/11	111mSv/hr				
3B	90	Ta #36						
3C								
4A						-		
-77			02/09/10	160mSv/hr				
4B	76	Nb #4	11/10/11	3.89mSv/hr	Assayed			
40	70	IND #4	11/10/11	3.0911134/111	Assayeu			
4C								
40								
						-		
5A								
			01/11/11	230 mSv/hr				
5B	85	Nb #5						
			06/11/12	152mSv/hr				
5C	95	Nb #6				1		

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring and cable lifting setup. This ring must be locked with a thin piece of metal before shipping.

Tray #	Pail #	Target	Installed (m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
6A								
			08/02/12	226 mSv/hr	Bolts might be contaminated			
6B	97	Ta#38						
			07/25/11	411mSv/hr				
6C	88	Ta#35						
			06/10/10	116mSv/hr				
7A	75	Ta#31	12/15/11	4.17mSv/hr	Assayed			
			11/16/11	239mSv/hr				
7B	92	TaC#1						
			08/25/10	292mSv/hr				
7C	81	ZrC#5	12/15/11	13.7mSv/hr	Not Assayed			
8A								
		T "00	07/16/10	124mSv/hr				
8B	78	Ta#32						
00								
8C	Descripti	on of Hom	Data Lantalla I		Comments			Commonto
Tray#	Description of Item		Date Installed	<u> </u>	Comments	Date Removed	Reading(mSv/Hr)	Comments
	Used source tray		-	5.6 to 16.4 mSv/hr thru				
	from TM #2		_					
				360°				
			-					
•			04/45/00					
9	Hand anyman from		01/15/09	4.00 to 0.50	The server travers			
	Used source tray			1.66 to 3.50	The source tray was			
	from TM #1			mSv/hr thru	taken apart for inspection			
			-	360∘				
			-					
10			05/12/11					
10		us tales at	05/12/11		4 (444) in used under lid vice			

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.