## State of the ISAC Mini Storage Vault as of November 14 2012

Pail #	Target	Date Installed(m/d/y)	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
				Last, back of the mini vault			
87	SiC #25	11/14/12	4.69 mSv/hr				
					_		
82	Ta #34	11/14/12	4.33 mSv/hr				
78	Ta #32	11/14/12	4.79 mSv/hr				
					_		
76	Nb #4	11/14/12	3.89 mSv/hr				
				First, front of mini vault	_		
75	Ta #31	11/14/12	4.17 mSv/hr				
					-		
All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.							
All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.							