## State of the ISAC Mini Storage Vault as of July 31 2013

Pail #	Target	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
			3.86mSv/hr	Back of Mini storage			
98	UO#3	07/31/13					
			1.89mSv/hr	Middle Back			
93	UC <sub>x</sub> #3	07/31/13					
			2.26mSv/hr	Middle			
102	UC #5	07/31/13					
			3.18mSv/hr	Middle Front			
83	SiC #23	07/31/13					
			0.913mSv/hr	Front			
99	UC <sub>x</sub> #4	07/31/13					

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.