State of the ISAC Mini Storage Vault as of February 3 2014

Pail #	Target	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
				Back of the mini storage			
101	NiO #1	02/04/14	1.50mSv/hr	(fourth)			
				Third			
85	Nb#5	02/04/14	3.05mSv/hr				
				Second			
92	TaC#1	02/04/14	3.55mSv/hr				
				First			
81	ZrC#5	02/04/14	2.65mSv/hr				
All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.							
All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.							