State of the ISAC Mini Storage Vault as of June 12 2014

Pail #	Target	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
				Back of mini storage			
113	UC _x #8	06/12/14	1.94mSv/hr				
				Middle back			
110	UC _x #7	06/12/14	1.95mSv/hr				
				Middle			
108	UC _x #6	06/12/14	1.65mSv/hr				
				Middle front			
105	SiC #28	06/12/14	2.02mSv/hr				
				Front or mini storage			
95	Nb #6	06/12/14	2.16mSv/hr				
All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.							
All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.							