State of the ISAC Mini Storage Vault as of June 30 2016

| Pail # | Target | Date Installed | Reading (mSv/Hr) | Comments | Date Removed Reading(mSv/Hr) | Comments |
|--|--------|----------------|------------------|---|------------------------------|----------|
| | | | | back of the vault | | |
| 128 | UC #13 | 06/20/16 | 1.28mSv/hr | installed as a spot gap due to vault door | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted. | | | | | | |
| All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping. | | | | | | |