State of the ISAC Mini Storage Vault as of May 2 2017

Pail #	Target	Date Installed	Reading (mSv/Hr)	Comments	Date Removed	Reading(mSv/Hr)	Comments
				Back of vault			
140	UC#16	05/02/17	1.58mSv/hr				
136	UC#15	05/02/17	0.873mSv/hr				
				Centre of vault			
147	UC#18	05/02/17	3.14mSv/hr				
142	UC#17	05/02/17	1.97mSv/hr				
				Front of vault			
107	Ta#40	05/02/17	2.74mSv/hr				

All readings are taken at 1m from centre of pail. Sealant (111) is used under lid rim. No contamination found unless other wise noted.

All lids have the lever lock ring. This ring must be locked with a thin piece of metal before shipping.