


Loc	Target	Pail	Assay 1 [mSv/h]	A1 date	Assay 2 [mSv/h]	A2 date	Assay 3 [mSv/h]	A3 date	Assay 4 [mSv/h]	A4 date	Assay 5 [mSv/h]	A45date	Assayed
1A													
1B	UC#27	218	22.9	10/9/2019	4.2	12/5/2019							Assayed
1C	C#1	237	0.2	8/27/2020									0
2A	Nb#8	168	71.1	8/2/2018	2.7	11/4/2019							Assayed
2B	SiC#33	141	295.0	8/25/2016	25.1	3/20/2017	7.5	3/23/2018	4.5	11/4/2019	3.4	12/9/2019	Assayed
2C	Ta#56	169	251.0	8/30/2018	9.1	11/4/2019							Measured
3A	ZrC#8	217	205.0	10/2/2019	74.8	12/10/2019							Measured
3B	SiC#37	165	25.8	5/5/2018	3.9	12/10/2019							Assayed
3C	Ta#58	211	311.0	8/19/2019	52.5	12/10/2019							Measured
4A	Ta#59	220	121.0	11/8/2019									0
4B	SiC#38	205	22.2	12/3/2019									0
4C	SiC#39	227	30.6	3/6/2020									0
5A	SiC#36	151	190.0	8/3/2017	21.0	3/23/2017	6.0	12/11/2019					Measured
5B	Ta#54	157	119.0	11/13/2017	20.5	3/23/2018	3.9	12/10/2019					Assayed
5C	Ta#53	164	244.0	9/28/2017	32.7	3/23/2018	7.2	12/10/2019					Measured
6A	UC#29	225	22.4	2/7/2020									0
6B	UC#25	204	12.8	1/11/2019	1.6	11/4/2019	1.3	12/11/2019					Assayed
6C	Ta#48	139	201.0	7/11/2016	7.3	3/20/2017	5.6	3/23/2018	3.6	11/4/2019	3.6	12/12/2019	Assayed
7A	Ta#55	161	30.4	4/16/2018	4.0	12/9/2019							Assayed
7B													
7C	SiC#35	144	228.0	11/24/2016	18.5	3/20/2017	4.4	3/23/2018	2.9	12/5/2019			Assayed
8A													
8B	Ta#51	149	144.0	6/12/2017	7.7	3/23/2018	3.6	11/4/2019	3.7	12/9/2019			Assayed
8C	Ta#57	174	139.0	11/30/2018	8.2	11/4/2019							Measured
9													
	TM4 optics tray 2018.		1.9	6/14/2018									
	TM2 source tray 2019												
10													
	TM4 Source tray		22.1	6/10/2019									

 Need to change pail to new design

Comment

0

Contains broken

0

0

0

This pail also contains,

0

0

0

Check for contamination

Contamination might be

0

0

0

0

This pail is one with the

0

0

0

0

0

In Source Tray Box

7.5 to 22.1 mSv/hr on
360 rotation.
