Loc	Target	Pail	Assay 1 [mSv/h]	A1 date	Assay 2 [mSv/h]	A2 date	Assay 3 [mSv/h]	A3 date	Assay 4 [mSv/h]	A4 date	Assay 5 [mSv/h]	A5 date	Assayed	Comment
1A	UC#45	292	19.5	2024-07-18									0	Contains the target material from UC#44
1B														
1C														
2A	UC#43	289	22.6	2024-02-14									0	** CRITICAL NOTE ** This pail needs a serialized lifter ID sticker attached to it. Install prior to F-308 loading. Contact Adam Newsome for details.
2B	Ta#65	284	41.0	2023-11-22									0	Note: *
2C														
3A	TiC#5	279	40.0	2023-06-21	6.8	2023-10-30							Measured	Note: *
3B	SiC#46	293	111.0	2024-08-14									0	0
3C	SiC#45	280	138.0	2023-07-27	32.6	2023-10-30							Measured	Note: *
4A	Nb#10	295	0.2	2024-08-26									Measured	0
4B	TiC#7	294	82.3	2024-08-21									0	0
4C	C#4	277	164.0	2022-11-24	4.1	2023-10-31							Measured	Note: *
5A	Ta#68	300	429.0	2024-12-05									0	0
5B	Ta#66	290	45.2	2024-01-01	27.0	2024-05-03							0	**CRITICAL NOTE ** before this pail gets shipped, parasitic target MUST be removed. Plan to remove it prior to moving this pail to mini-storage. Contact Carla Babock for details. Note: this pail is the first one of the next generation (Rev D) which has a lid certified as a lifting device. Parastic Target removed, Pail was repacked and is in #290 from #285.
5C	Ta#64	273	86.6	2022-08-18	4.1	2023-10-30							Measured	
6A	TiC#6	232	151.0	2023-08-23	52.0	2023-10-31							Measured	Note: *
6B	UC#42	282	34.9	2023-09-01	7.0	2023-10-31							Measured	Note: *
6C 7A	Ta#62	256	58.0	2021-09-17	16.9	2022-01-27	3.6	2022-12-16	3.5	2023-10-30			Measured	2022-12-16 moved from 7A to 7B in vault AN Pail placed back in 7ATC Disc in bottom of pail was not installed pail will need repacking. This pail is likely contaminated and also contains 2A2M19. Note:*
7B	Nb#11	283	65.7	2023-10-06	30.3	2023-10-30							Measured	Note: *
7C														
8A	Tic#9	299	92.1	8 Nov 2024									Measured	0
8B	TiC#8	297	2.7	2024-10-11									0	0
8C	Ta#67	296	105.0	2024-10-11									0	0
9	TM4 optics tray 2018. TM2 source tray 2019		1.9	2018-06-14	14.0	2019-03-01	7.1	2020-11-02						In Source Tray Box. The 1.9 mSv/Hr value is just for the optics tray. All other values are for both Optics and Source tray.
10	TM4 Source	e tray	22.1	2019-06-10										7.5 to 22.1 mSv/hr on 360 rotation.

Need to change pail to new design

Note: * This pail is of previous revision, not certified as lifting device. Prior to shipping, a 3" loop must be crimped at the end of the wire rope.